

Beslow, Mike

From: Renner, Cordell <Cordell.Renner@tetrattech.com>
Sent: Tuesday, February 24, 2015 11:01 AM
To: Beslow, Mike
Subject: RE: Lab Results

OA-MW-10 and MW-10-pp(post purge) is the well in the center of the secondary containment. OA-S5-03-0219 (they thought my second S was a 5) was taken next to OA-SS-0213-02 from the sampling done on Feb 13th. OA-MH-05-0219 was taken from the manhole in the center of the secondary containment. I'm not in the office to make a map of the points, I can get that tomorrow for you if that would work.

Cordell C. Renner | Environmental Scientist
1S. Wacker Drive | Chicago, Illinois 60606 | www.tetrattech.com
Direct: 312.201.7759 | Cell: 847.913.2904

Think Green - Not every email needs to be printed

From: Beslow, Mike [mailto:beslow.mike@epa.gov]
Sent: Tuesday, February 24, 2015 10:54 AM
To: Renner, Cordell
Subject: RE: Lab Results

Can you provide a rundown of location of each sample? Maybe on a map?

Mike Beslow

On-Scene Coordinator
US EPA, Region 5
77 W Jackson (SE-5J)
Chicago, IL 60604
voice: (312)353-8678
fax: (312)582-5139

From: Renner, Cordell [mailto:Cordell.Renner@tetrattech.com]
Sent: Tuesday, February 24, 2015 10:51 AM
To: Beslow, Mike
Subject: Lab Results

1502765- is the first set of samples from 02/11-0213
1502920- is the second set of samples

We did a quick QC on them and it all looked good. When the Level 4 packages come in we will do the complete QC.

Cordell C. Renner | Environmental Scientist
1S. Wacker Drive | Chicago, Illinois 60606 | www.tetrattech.com
Direct: 312.201.7759 | Cell: 847.913.2904

Think Green - Not every email needs to be printed